Exhibit 4: Marquis Theater

Exhibit 4A: Entrances

Nederlander shall maintain the entrance to the Theater, including but not limited to the automatic accessible entry doors, in the same condition as set forth on Exhibit 4A (i.e., in the same condition as they existed for the Government's inspection conducted on May 3, 2011).

Exhibit 4B: Architectural Modifications

Nederlander shall make the architectural modifications set forth in Exhibit 4B. Nederlander shall further ensure that patrons of the Theater have access to a designated accessible restroom at the Marriott Marquis Hotel, and post signage indicating the location of that restroom.

Exhibit 4C: Seating


Nederlander shall implement the seating plan attached hereto as Exhibit 4C.

Wheelchair and Companion Seating:

- 1. Nederlander shall maintain the eight existing wheelchair and companion seating locations on the Orchestra level: at Y2, Y3, Y4, Y5, Y102, Y103, Y120, and Y121, with Y1, Y2, Y7, Y8, Y101, Y104, Y119, and Y125 being companion seating locations.
- 2. Nederlander shall add two wheelchair seating locations on the Orchestra level at Y14/Y12/Z8/Z6 and Y13/Y11/Z5/Z7, with Y10 and Y9 being companion seating locations.


Aisle Transfer Seats:

3. Nederlander shall add sixteen new aisle transfer seats on the Orchestra Level at K2, F18, S28, T2, A2, P125, P101, T1, S27, K1, F17, A1 and on the Mezzanine Level at K34, L2, L1 and K33.




4. MARQUIS THEATER BOX OFFICE PLAN


EXISTING CONDITIONS N.T.S




4. MARQUIS THEATER MARRIOT MARQUIS HOTEL NORTH - MEN TOILET PLAN EXISTING CONDITIONS N.T.S



4. MARQUIS THEATER MARRIOT MARQUIS HOTEL SOUTH - LADIES TOILET PLAN EXISTING CONDITIONS N.T.S



4. MARQUIS THEATER MARRIOT MARQUIS HOTEL SOUTH - MEN TOILET PLAN EXISTING CONDITIONS N.T.S



4. MARQUIS THEATER MARRIOT MARQUIS HOTEL NORTH - LADIES TOILET PLAN EXISTING CONDITIONS N.T.S

Case 1:14-cv-00340-KPF Document 2-4 Filed 01/28/14 Page 7 of 12 Exh. 4B Architectural Modifications to Marquis Theater

Line #	Location Description	Existing Condition	Barrier Removal	1991 Standards Reference	Architectural Modification
1	Entire Facility	There are no raised letter and Braille exit signs in the Facility. Emergency exits with signs that are readable by the public are considered permanent rooms or spaces and are required to have raised letter and Braille signs on them mounted at 60" AFF on the latch side of the door.	requirements for signage characteristics, particularly raised characters and Braille, as well as location and	4.1.3(16)(a) 4.30.1 4.30.4 4.30.5 4.30.6	Defendant will provide compliant signage.
2	Entire Facility	There are enough alarm pull stations at exit doors and at key points on the stage and trap level to indicate that an audible alarm system is in place in both public and backstage areas of the facility. However, there are no visual signaling devices as required. Approximately three dozen devices will be required in the backstage areas alone.	alarm signal appliances where required.	4.1.3(14) 4.28	Defendant has installed visual alarm system where required.
3	Entire Facility	Audible alarm system not tested to verify compliance with ADA standards.	Verify compliance with ADA standards for volume, etc.	4.1.3(14) 4.28.2	Defendant has verified compliance, and will continue to do so annually.
4	Main Lobby	Existing ramp which serves as part of an accessible route does not have handrails. There are no handrails on either ramp in the lobby.	Install compliant handrails on both sides of ramp.	4.8.5 4.26 Fig. 17 Fig. 39	Defendant has provided handrails during the course of the investigation.

Case 1:14-cv-00340-KPF Document 2-4 Filed 01/28/14 Page 8 of 12 Exh. 4B Architectural Modifications to Marquis Theater

Line #	Location Description	Existing Condition	Barrier Removal	1991 Standards Reference	Architectural Modification
5	Main Lobby (Concession Counter)	or distribution of goods	Alter at least 1 counter of each type, on each level, such that a section at least 36" long is not higher than 36" AFF, and is on an accessible route.	7.2(1) 7.2(2) 4.3	Defendant will include accessible sections in operating concession counter.
6	Main Lobby (Souvenir Counter/Cart)	or distribution of goods	Alter at least 1 counter of each type, on each level, such that a section at least 36" long is not higher than 36" AFF, and is on an accessible route.	7.2(1) 7.2(2) 4.3	Defendant will include accessible sections in operating concession counter.
7	Main Lobby (Upper Concession Stand)	Sales, service or information counter higher than 36" AFF at cash register(s) for sales or distribution of goods or services to the public. The upper concession stand is at 42" AFF.	of each type, on each level, such that a section at least 36" long is not higher than	7.2(1) 7.2(2) 4.3	Defendant will include accessible sections in operating concession counter.
8	Mezzanine Lobby - Hotel Level (Toilet Rooms)	Existing toilet rooms do not provide the required turning space, clear floor space at fixtures, maneuvering clearance(s) at door, or accessible stall (if applicable).	should be provided somewhere in the facility if these are not	4.22 4.13 4.2.3 4.17 4.26	Defendant shall inform patrons that the Theater lacks any restroom facilities, and shall post signage, and indicate on its website and in any program guide the location of the nearest accessible restroom facility.


Case 1:14-cv-00340-KPF Document 2-4 Filed 01/28/14 Page 9 of 12 Exh. 4B Architectural Modifications to Marquis Theater

Line #	Location Description	Existing Condition	Barrier Removal	1991 Standards Reference	Architectural Modification
9	Mezzanine Lobby - Hotel Level (Mezzanine Level Concession Stand)	Sales, service or information counter higher than 36" AFF at cash register(s) for sales or distribution of goods or services to the public. The upper concession stand counter is at 42" AFF.	of each type, on each level, such that a section at least 36" long is not higher than	7.2(1) 7.2(2) 4.3	Defendant will include accessible sections in operating concession counter.
10	Ticket Office	No signage is provided at the ticket office notifying patrons of the availability of aisle seats without armrests, or with folding or removable armrests on the aisle side.	Install required signage at the ticket office and, preferably, in main lobby, too.	4.1.3(19)(a)	Defendant will provide compliant signage.
11	Ticket Office	Sales, service or information counter higher than 36" AFF at cash register(s) for sales or distribution of goods or services to the public. Ticket counters are at 42½" at AFF.	a section at least 36" long is not higher than 36" AFF, and is on an	7.2(2) 4.3	Defendant will include accessible sections in operating concession counter.
12	Ticket Office	No assistive listening system was found during survey and there was no signage at the ticket office or other apparent location notifying patrons of the availability of an assistive listening system.	the required number of	4.30, Fig. 43(d)	Defendant has provided ALS and will continue to do so.

Case 1:14-cv-00340-KPF Document 2-4 Filed 01/28/14 Page 10 of 12 Exh. 4B Architectural Modifications to Marquis Theater

Line	Location	Existing Condition	Barrier Removal	1991 Standards	Architectural
#	Description			Reference	Modification
13	Ticket Office	Existing accessible	If phones become	4.1.3(17)	Defendant will remove
		public pay	usable by anyone (if	4.2.4	existing payphones.
		telephones are not	dial tone is restored),	4.2.5	
		hearing aid compatible	remove one existing	4.2.6	
		and have no volume	phone and replace it	4.4	
		controls. There are 2	with a compliant phone	4.30.7	
		pay telephones, both	or bring one of the	4.31.2	
		with parallel approach	existing phones into	4.31.3	
		at 54" AFF. Telephones	compliance.	4.31.4	
		have no dial tone, are		4.31.5	
		not hearing aid		4.31.6	
		compatible, and have no		4.31.7	
		volume controls.		4.31.8, Fig. 44	
14	Ticket Office	Clearance width less	Modify at least one	4.1.3(7)	Defendant will provide
		than 32" at doorway (or	door to provide 32"	4.13.5	complaint door and
		active leaf of double	minimum clear width.	Fig. 24	will repair concrete
		door). Doors are 36"	Install signs at		pavement.
		wide but have only 29"	inaccessible entrances		
		clear width due to hinge	directing users to		
		point locations at	accessible entrance(s).		
		Marquis Alley Hotel			
		entrance. (7th Avenue			
		doors are similar.) The			
		concrete in the Marquis			
		Alley will need to be			
		patched/repaired.			
1					


ARCHITECTS • ENGINEERS • CONSULTANTS



- Legend
- EXISTING AISLE TRANSFER SEAT
- **NEW AISLE TRANSFER SEAT**
- EXISTING WC/C LOCATION
- NEW WC/C LOCATION

NOTE: At the Marquis, 5 wheelchair seating and companion locations, and all 16 aisle transfer seating locations, are sold at the same price as adjacent seating locations in the same row. 5 wheelchair seating and companion locations are sold at the lowest price.

ARCHITECTS • ENGINEERS • CONSULTANTS



- Legend
- EXISTING AISLE TRANSFER SEAT
- NEW AISLE TRANSFER SEAT
- EXISTING WC/C LOCATION
- NEW WC/C LOCATION

NOTE: At the Marquis, 5 wheelchair seating and companion locations, and all 16 aisle transfer seating locations, are sold at the same price as adjacent seating locations in the same row. 5 wheelchair seating and companion locations are sold at the lowest price.